

Project Review:

SC2000-05

Church in Minneapolis: church building

Project Location:

Brooklyn Park

MAP:

5

6241 West Broadway

Pond SW corner outlets overland across adjacent property. Verify flowpath to SS

Inlet (s): Upper riprap area is blocking runoff from parking lot to pond. Minor erosion on upper end of lower riprap area.

Outlet(s): Baffled weir, no obstruction.

Basin(s): Should be permanent pool, but the pond is completely dry.

Inspection Date: October 14, 2004

Comments: Drainage to south is acceptable. No recommended improvements.



Looking southwest



Looking north