

**Project Review:**

**SC2003-01**

Way Addition: office condos and office building

**Project Location:**

MAP: 1

Maple Grove

NE quad Fish Lake Rd and Wedgewood Rd

1 pond: NE corner abutting I494 ROW. Approved with 4:1 side slopes and no safety bench

**Inlet (s):** The basin has two inlets. Both inlets have sediment and trash in them. The riprap pads also have sediment and trash in them. Maintenance is required on the inlets and the riprap pads to remove sediments and trash.

**Outlet(s):** There is no skimming provided at this time because the permanent pool volume is below the crown of the outlet pipe, although when the pool volume is higher it appears skimming is provided. No maintenance on the control structure is required at this time. Emergency overflow appears to be provided. There is a stabilized spillway with river rock.

**Basin(s):** A permanent pool is provided. Estimated depth to be a couple of feet. The side slopes are vegetated except for at the waterline. There is trash all around the water line. There is a lack of vegetation at the water line.

**Inspection Date:** October 6, 2004

**Comments:** Remove sediment and trash from the pond. Reseed pond side slopes if vegetation is still lacking.

