





Pond 1 - erosion at southwest inlet



Pond 4 - looking northwest - outlet grate looks high



Pond 3 - looking southeast



Pond 4 - inlet pipe buried?