

Project Review:

WM2003-07

Shadowbrook: 92 single family units

Project Location:

Brooklyn Park

MAP:

SW quad 109th & Noble
1 pond, N side by 109th

Inlet (s): Severe erosion at southeast inlet of main pond.

Outlet(s): Outlet not located.

Basin(s): Side slopes not vegetated. Erosion of side slopes around pond.

Inspection Date: August 25, 2005

Comments: Small pond at intersection - what is purpose of pond? There is an inlet pipe at northwest corner, but pond is not connected to main pond.

Repair erosion at southeast inlet and around pond. Reseed side slopes of pond.



Erosion at southeast inlet



Main pond-background; small pond-foreground