

Project Review: SC2000-21
Ernst Movers: commercial development

Project Location: MAP: 20
Brooklyn Park
NE quad 85th & Jefferson Highway
1 pond N side

Inlet (s): Southwest corner the riprap is eroded. There is also trash in southwest corner. Significant erosion on north side. PVC drain now connects for a paralell roof drain.

Outlet(s): No visible outlet. Deep pond sized for back-to-back 100-year event?

Basin(s): Depth 2-3'. Erosion by roofdrains. Maintenance required.

Inspection Date: August 24, 2005

Comments: Stabilize multiple areas of erosion on north side of pond.



Northside erosion



Southeast inlet looking west