

**Project Review:** SC2000-22  
Palmer Lake WQ & Trail Project: wetland alteration plan

**Project Location:** MAP: 21  
Brooklyn Center  
Adjacent to East Palmer Lake Park  
Replacement of drainage channel with 2 cell wetland mitigation

**Inlet (s):** Inlets well stabilized with grouted riprap.

**Outlet(s):** Outlets directly to wetland

**Basin(s):** Vegetation on east side of pond not established due to water level fluctuations. Pond is wetland mitigation and issue addressed in mitigation annual reports.

**Inspection Date:** October 12, 2004

**Comments:** Establish vegetation on east side of pond as required in annual wetland monitoring report.



Inlet



East side; vegetation not established