

**Project Review:** SC2002-08  
Glacier Vista, 27-acre single- and multiple-family housing development

**Project Location:** MAP: 1  
Plymouth  
Northeast corner of Pomerleau Lake of Juneau Lane E.  
2 ponds: Ponds are adjacent to the lake.

**Inlet (s):** The pond inlets are both stabilized with riprap. They are clear of debris and no maintenance is required at this time.

**Outlet(s):** The outlet is also clear of debris. Skimming is provided. No maintenance is required at this time. There is a stabilized emergency overflow spillway provided. It should be removed and reinstalled to make it flush or lower than the rest of the pond bank. Build it per plan.

**Basin(s):** A permanent pool is provided; the estimated depth is 2 to 4 feet. The side slopes are vegetated. No maintenance is required.

**Inspection Date:** October 12, 2004

**Comments:** The development is behind schedule and only a couple of homes and one pond have been built at the time of this report.

No recommended improvements.

