

Project Review: SC2003-08  
Crystal Shopping Center Redevelopment: new buildings

Project Location: MAP: 9  
Crystal  
SW quad Bass Lake Rd and Broadway  
1 pond on south side discharging to an infiltration basin that discharges into city SS.

**Inlet (s):** West Pond - Bank failure adjacent to riprap. Erosion at sides of riprap at west and central inlets. Remove sediment from west and central areas of pond.

East Pond - No riprap at inlet from west pond.

**Outlet(s):** West Pond - Outlet in good condition.

East Pond - OK, outlet to city storm sewer.

**Basin(s):** West Pond - Remove silt fence from west pond. Should have permanent pool.

East Pond - No permanent pool. Concrete washout area at northeast corner of pond.

**Inspection Date:** October 14, 2004

**Comments:** Remove silt fence from west pond. Repair erosion and bank failure of west pond.  
Remove concrete from east pond. Scarify soil to a depth of 18-24" to ensure infiltration will occur.



West Pond



East Pond