

Project Review:

SC2003-04

Navarre Corporation: construction 100,000 sf building

Project Location:

MAP:

4

New Hope

N side 49th at intersection 49th & Quebec Ave

1 pond in NW corner that discharges to an existing city pond NE b/ween site & RR

Inlet (s): Inlet at southeast corner no riprap. Add riprap at southeast corner inlet

Outlet(s): Submerged outlet. 4-6" orifice is good. Remove silt fence from outlet manhole grate.

Basin(s): Vegetation still emerging, may need to re-seed. Pond depth approximately 5'.

Inspection Date: October 14, 2004

Comments: Install riprap at southeast pond inlet. Remove silt fence from outlet manhole. Stabilize outlet pipe flared end section to northeast. Re-seed pond side slopes, as necessary.



Looking northeast



Pond outlet pipe flared end section