

Project Review:

WM2003-03

TH 169, 120th & Business Park Blvd: turn lanes, lights, frontage rd

Project Location:

Champlin

MAP:

TH 169 & 120th

Discharges to 3 existing ponds, small wetland mitigation

Inlet (s): OK, inlets stabilized and not obstructed.

Outlet(s): OK, submerged outlet pipes provided for existing ponds.

Basin(s): OK, ponds are well vegetated with permanent pools. Sediment control silt curtain remains from construction.

Inspection Date: August 24, 2005

Comments: Remove silt curtain from southwest pond.

