

Project Review: SC2000-02
Boone Industrial Center: industrial development & wetland alteration

Project Location: Brooklyn Park
7624 Boone Ave N
1 pond on S side discharges to wetland mitigation site

MAP: 2

Inlet (s): Inlet stabilized and in good condition.

Outlet(s): Outlets via a submerged outlet to the adjacent wetland.

Basin(s): Sides well established and permanent pool is established. Substantial cattail growth in basin.

Inspection Date: October 14, 2004

Comments: No recommended improvements



Inlet

