

**Project Review:**

**SC2000-03**

Humboldt Greenway: stormwater mgmt plan, riffle installation

**Project Location:**

MAP: 3

Minneapolis

Humboldt between Victory Memorial & 53rd

4 ponds: A: behind senior housing B: b/w 48th & 49th; D: N of 49th; C: W side of creek S of 49th; grit chamber

C: N of Shingle Creek Dr on Humboldt; 2 riffles, 47th & 49th Aves

**Inlet (s):**

Inlets to sediment ponds not stabilized with riprap. Good vegetation has prevented erosion.

**Outlet(s):**

Weir from sediment ponds and creek are good.

**Basin(s):**

Depth 1-3'

**Inspection Date:**

November 3, 2004

**Comments:**

Riffles installed and functioning. Emergency overflow is to creek.

No recommended improvements.

