

Project Review:

SC2000-07

SAFECO Products: expansion of existing bldg & parking

Project Location:

MAP: 7

New Hope

9300 W Research Center Rd

Pond NE corner; swale on N side of bldg lined with drain tile; V2B1 SW corner


Inlet (s): Erosion at side of riprap from roof drains. Stabilize slopes downstream from roof drains.

Outlet(s): 12-15" RCP. Condition of outlets are good.

Basin(s): Depth 4-5'

Inspection Date: November 3, 2004

Comments: Drintile end located and appears to be functioning. Remove sediment from V2B1. Stabilize slopes downstream from roof drains.



Basin



Slopes downstream from roofdrains