

Project Review:

SC2000-18

Joslyn Addn: construction of Wickes warehouse

Project Location:

MAP:

17

Brooklyn Center

Between Azelia & Middle Twin Lake, S of CP Rail
1 pond behind (W) of warehouse

Inlet (s): OK, inlets stabilized and vegetated.

Outlet(s): OK, permanent outlet provided with submerged outlet to provide skimming.

Basin(s): OK, well vegetated and about 2-4' deep.

Inspection Date: August 24, 2005

Comments: No recommended improvements.

