

**Project Review:** SC2002-11  
Hickok North Lot/ Office Showroom

**Project Location:** MAP: 8  
Maple Grove  
NW quadrant 63rd Ave and Sycamore Ln N  
Site discharges to city pond NW of site

**Inlet (s):** The inlets were not located. Unable to confirm if they are stabilized with riprap or that they are clear of debris. Clear vegetation from around the inlets.

**Outlet(s):** The outlet was not located. It is overgrown with vegetation. Remove debris from around the outlet of the pond. The pond flows northwest to a regional pond. There is no evidence of localized erosion.

**Basin(s):** The basin has a permanent pool of water. The estimated depth of the pond is 1 foot. The side slopes are vegetated and no maintenance is required.

**Inspection Date:** October 7, 2004

**Comments:** The northwest corner of the property is about to be developed. The site has been ringed with silt fence, and it looks like they are getting ready to open the ground up.

Remove vegetation and debris from inlets and outlets; stabilize with riprap.

