

Project Review:

WM2002-13

New Earle Brown Elementary School

Project Location:

MAP:

Brooklyn Center

NW quad Humboldt & 59th Ave
2 ponds

Inlet (s): **West Pond** - Sediment deposition on west inlets. Erosion adjacent to inlet pipes.

East Pond - OK, stabilized and no obstructions.

Outlet(s): **West Pond** - OK, submerged outlet pipe.

East Pond - OK, submerged outlet pipe.

Basin(s): **West Pond** - OK, vegetated with permanent pool.

East Pond - OK, vegetated with permanent pool.

Inspection Date: August 25, 2005

Comments: **West Pond** - Remove sediment deposition on west inlets. Repair erosion adjacent to inlet pipes.

East Pond - No recommended improvements



West Pond



East Pond