

Project Review:

WM2003-09

Noble Acres: 38 single family homes

Project Location:

MAP:

Brooklyn Park

NE quad 105th and Noble

1 pond, emergency overflow to the wetland in the SE corner

Inlet (s): Severe erosion at northeast inlet.

Outlet(s): OK, submerged outlet pipe. The pond drains to the southeast wetland, but the pipe outlet was not located in the wetland.

Basin(s): OK, well vegetated with permanent pool.

Inspection Date: August 31, 2005

Comments: Repair erosion at the northeast inlet.



Pond looking south - erosion in foreground



Northeast inlet