

Project Review:

WM2003-12

Prairie Gardens: 50 single family homes

Project Location:

MAP:

Brooklyn Park

SE quad Douglas and 107th Pkwy
1 pond discharges to Oxbow Creek II wetland

Inlet (s): OK, stabilized and not obstructed.

Outlet(s): OK, submerged outlet pipe - overflow to Oxbow wetland.

Basin(s): Vegetated with permanent pool, but severe erosion at southwest corner of pond.

Inspection Date: August 25, 2005

Comments: Repair severe erosion at southwest corner of pond.



Erosion at southwest corner

