




Long term plan: restore natural form and function with ecological restoration principles

Thin riparian trees

Restore gravel/cobble substrate and add large woody debris, other habitat structures



2004 Twin Cities Metro Area
0.3 Meter Resolution Aerial Photography
US Geological Service

L:\1240\1240-33\apr\reach_1_ft_aerials

SHINGLE CREEK CORRIDOR STUDY

Reach 6 Candlewood to Broadway


Wenck
 Wenck Associates, Inc. 1800 Pioneer Creek Center
 Environmental Engineers Maple Plain, MN 55359-0249

July 2005

Figure 18