



Numerous open drainage channels discharge to basin

"Island" area cultivated during 1930s drought

Old ditch channel now overgrown

Palmer Lake



2004 Twin Cities Metro Area
0.3 Meter Resolution Aerial Photography
US Geological Service



L:\1240\1240-33\apri\reach_1_ft_aerials

SHINGLE CREEK CORRIDOR STUDY

Reach 4 Palmer Lake


Wenck
 Wenck Associates, Inc. 1800 Pioneer Creek Center
 Environmental Engineers Maple Plain, MN 55359-0249

July 2005

Figure 6